

Machos para máquina - HSS

BSW 295/1 295/2 295/3 - DIN 2183 haste passante rosca Whitworth grossa: BS 84 (DIN 11)



POT 295/1 código 29510...



POT 295/1 TIN código 29513...



STF 295/2 código 29520...



STF 295/2 TIN código 29523...



MT 295/3 código 29530...



MT 295/3 TIN código 29533...

Bitola	1/4	5/16	3/8	7/16	1/2	9/16	5/8	3/4	7/8
Passo fios/pol.	20	18	16	14	12	12	11	10	9
Compr. total	80	90	100	100	110	110	110	125	140
Compr. rosca 295/1	19	22	22	24	29	30	32	34	34
Compr. rosca 295/2	15	17	19	22	25	25	28	30	34
Compr. rosca 295/3	19	22	22	24	29	30	32	34	34
Ø haste	4,5	6	7	8	9	11	12	14	18
quadrado	3,4	4,9	5,5	6,2	7	9	9	11	14,5
Ø broca	5	6,4	7,8	9,2	10,4	12	13,4	16,3	19,2

Referência	Código	07277	07283	07289	07295	07301	07307	07313	07319	07325
295/1										
295/2		07278	07284	07290	07296	07302	07308	07314	07320	07326
295/3		07279	07285	07291	07297	07303	07309	07315	07321	07327
295/1 TIN		07280	07286	07292	07298	07304	07310	07316	07322	07328
295/2 TIN		07281	07287	07293	07299	07305	07311	07317	07323	07329
295/3 TIN		07282	07288	07294	07300	07306	07312	07318	07324	07330

Bitola	1"	1.1/8	1.1/4	-	-	-	-	-	-
Passo fios/pol.	8	7	7	-	-	-	-	-	-
Compr. total	160	180	180	-	-	-	-	-	-
Compr. rosca 295/1	38	45	50	-	-	-	-	-	-
Compr. rosca 295/2	38	44	44	-	-	-	-	-	-
Compr. rosca 295/3	38	45	50	-	-	-	-	-	-
Ø haste	20	22	25	-	-	-	-	-	-
quadrado	16	18	20	-	-	-	-	-	-
Ø broca	22	24,6	27,8	-	-	-	-	-	-

Referência	Código	07331	07337	07343	-	-	-	-	-
295/1									
295/2		07332	07338	07344	-	-	-	-	-
295/3		07333	07339	07345	-	-	-	-	-
295/1 TIN		07334	07340	07346	-	-	-	-	-
295/2 TIN		07335	07341	07347	-	-	-	-	-
295/3 TIN		07336	07342	07348	-	-	-	-	-